

Technical Bulletin #50

Revised and updated bulletin – Technical bulletin #42

Below is the revised information for the discontinued Technical Bulletin #42

The following Tint base and Pearl Powders are the only products still requiring a multiplier.

Tint Bases that currently require a multiplier

Endura SKU	Item Description	Multiplier
ITB0021	TB-21 RED	x 1.20

Pearl Powders currently require a multiplier (please note that ALL pearls require the multiplier)

Endura SKU	Item Description	Multiplier
ITB0040PWD	PEARL POWDER TB40PWD SUPER SILK 9120T MEARLIN	x 1.24
ITB0714	PEARLPOWDER EXT HI-LITE RED 439X MEARLIN	x 1.24
ITB0715	PEARLPOWDER EXT HILITE BLUE639X MEARLIN	x 1.24
ITB0716	SPARKLE GOLD 9212P MEARLIN PEARL POWDER TB43PWD	x 1.24
ITB0717	PEARL POWDER GREEN	x 1.24
ITB0718	PEARL POWDER VIOLET	x 1.24
ITB0739	PEARL POWDER EX SUPER GOLD 239Z MEARLIN	x 1.24
ITB0788	PEARL POWDER SUPER BRONZE	x 1.24
ITB0789	PEARL POWDER SUPER COPPER 9350Z MEARLIN	x 1.24

Discontinued Pearl Powders

ITB0779 PEARL POWDER RED RUSSET 559-Z (**ITEM IS NOW DISCONTINUED**)

NOTE

All other Endura tint bases are the NEW – HIGHER STRENGTH series and DO NOT require a multiplier

For any questions please contact your Endura representative or the Endura color lab @ **1-800-661-9930**.

Endura Manufacturing Co. Ltd.
12425 149th Street
Edmonton, Alberta T5L 2J6
Ph: 780-451-4242
www.endura.ca