

Technical Bulletin #52

Revised and updated bulletin – This bulletin supersedes Technical Bulletin #50

Below is the revised information for the discontinued Technical Bulletin #50

Endura has updated the color system to include the multiplier for formulas that use TB21 and Pearl Powders. As of Saturday May 14th 2016 you will no longer be adding the multiplier when using TB21 or Pearl Powders.

The formulas have also been adjusted to remove the corresponding amount of Clear 111.

Endura SKU	Item Description	Multiplier
ITB0021	TB-21 RED	x None
ITB0040PWD	PEARL POWDER TB40PWD SUPER SILK 9120T MEARLIN	x None
ITB0714	PEARLPOWDER EXT HI-LITE RED 439X MEARLIN	x None
ITB0715	PEARLPOWDER EXT HILITE BLUE639X MEARLIN	x None
ITB0716	SPARKLE GOLD 9212P MEARLIN PEARL POWDER TB43PWD	x None
ITB0717	PEARL POWDER GREEN	x None
ITB0718	PEARL POWDER VIOLET	x None
ITB0739	PEARL POWDER EX SUPER GOLD 239Z MEARLIN	x None
ITB0788	PEARL POWDER SUPER BRONZE	x None
ITB0789	PEARL POWDER SUPER COPPER 9350Z MEARLIN	x None

Discontinued Pearl Powders

ITB0779 PEARL POWDER RED RUSSET 559-Z (**ITEM IS DISCONTINUED**)

NOTE

All other Endura tint bases are the NEW – HIGHER STRENGTH series and DO NOT require a multiplier

For any questions please contact your Endura representative or the Endura color lab @ **1-800-661-9930**.

Endura Manufacturing Co. Ltd.
12425 149th Street
Edmonton, Alberta T5L 2J6
Ph: 780-451-4242
www.endura.ca