
Technical Bulletin #61 June 6, 2018

EP-2C Sealer Product Update

As Zinc Chromate has been found to be a health concern, Endura has removed it as a corrosion inhibitor from EP-2C Sealer and replaced it with a non-toxic additive that performs the same function.

EP-2C Sealer (FUA0650) has been replaced by EP-2C Sealer AC (FUA0675); component B will remain the same.

For any customers or distributors that have stock of EP-2C Sealer (FUA0650), please note that this product is still viable for use and sales until stocks have been depleted.

For any questions please call your Endura representative at 1-800-661-9930.

Endura Manufacturing Co. Ltd.
12425 149th Street
Edmonton, Alberta T5L 2J6
Ph: 780-451-4242
www.endura.ca